Off Road Only

ORO York clutch adaptor

Modification for York 3.6L application

ph 651.644.2323

www.offroadonlv.com

Thank you for your purchase. If you have this note in your kit then you have one of the York kits that runs the compressor off of the harmonic balancer.

We have learned since we developed this kit that there are some balancers that have a super sharp casting flash on them. This flash is a sharp edge on the inside of the opening where the "fingers" of the coupler will contact when the coupler is mated to the harmonic balancer. IF these edges are left sharp, then the installation of the coupler may cause the silicone to get cut and damaged or will simply cause a sharp edge for the abrasion to cause premature wear on the silicone and once the silicone is damaged then the hard rubber cushions molded into the silicone will suffer from abrasion as well.

The solution to a long life is simply grab a Dremel tool or die grinder and grind smooth the casting flash. How smooth? Run your fingers around the areas shown in yellow in the image



below. If you feel any sharp edges, that sharpness will become multiple with the force of the compressor. Smooth them edges until you can swipe your finger and not feel an edge. Also, the outer edge around the opening is known to be sharp as well, Dremel if necessary.